WARNING! COMBUSTIBLE LIQUID AND VAPOR. See Other Cautions On Back Panel.

LEAD FREE

Province Transmission Transm

DURALUX

Basic Use And Information

Duralux is the highest quality marine enamel available. The white stays white and colors bright and clear. It is made from alkyd resin for smoother leveling and higher gloss retention. If washes like glazed tile time after time and resists oil, gasoline and discoloration from harbor gases

Technical Information

Distance: On properly prepared surfaces, expect to cover from 400-500 square feet per gallon. Drying Time: Four hours, but slightly longer on damp or cold days. Allow 12-16 hours for hardening before repainting. Maximum VAC: 3.3 lbs/gal.

Surface Preparation

All surfaces must be free of moisture, wax, dirt, nust and other foreign matter. Remove any loose or peeling paint. Use sandpaper or power burshing to dull any existing gloss. Remove all dust by wiping surfaces with a clean cloth dampened with paint thinner. WARNINGI IF you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CANES SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN PREGNANT WORKEN SHOULD ALSO AVOID EXPOSURE. Wear a NICKH-approved respirator to control lead exposure. Clean up carefully with a HEPA wexum and a wet mop. Before you start, find out how to protect youself and your family by contacting the National Lead Information Hoftine at 1:800-424-LEAD or log on to www.exp.gov/lead.

Unpainted Surfaces:

- Wood Prime with Duralux Yacht Primer No. M741, apply two coats of Duralux.
- Steel: On clean, rust-free steel, apply two coats of Duralux Zinc Chromate Primer No. M739, apply two coats of Duralux.
- Aluminum: Pretreat with suitable wash primer. Apply one coat of Duralux Zinc Chromate Primer No. M739. Top with two full coats of Duralux.
- Fiber Glass: Wipe down with Acetone prior to sanding and after sanding. Top with two thin coats of Duralux.

Painted Surfaces:

■ Wood – Sand thoroughly, spot prime bare areas then apply two coats of Duralux. ■ Steel – Clean all bare areas to bright steel. Touch up with two coats of Duralux Zinc Chromate Primer No. M739. Top with two full coats of Duralux.

- Aluminum Touch up all bare areas with Duralux Zinc Chromate Primer No. M739. Top with two full coats of Duralux.
- Fiber Glass Wipe down with Acetone prior to sanding and after sanding. Top with two thin coats of Duralux.

Application

Method: Use brush, spray or roller.

Thinning: Not recommended. If thinning is desired, use either Paint Thinner 650 or xylene up to a half-pint per gallon.
Clean Up: Clean equipment with paint thinner.

CONTAINS PETROLEUM DISTILLATE

VAPOR HARMFUL MAY AFFECT THE BRAIN OR NERVOUS SYSTEM CAUSING DIZZINESS, HEADACHE OR NAUSEA CAUSES EVE, SKIN, NOSE AND THROAT IRRITATION NOTICE: Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage Intentional misuse by deliberately concentrating and inhaling the contents may be harments in or be failed on the solvent of the solven

Keep away from heat and flame. Do not smoke Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. Do not breathe vapors or spray mist. Use only with adequate wentilation. Ensure fresh air entry during application and drying If you experience eje watering, headache or dizziness or if air monitoring demonstrates vapor/mist levels are above applicable limits, war an appropriate, properly fitted respirator (NIOSH/MSHA approved) during and after application. Follow respirator manufacturer's directions for respirator use. Close container after each use Avoid contact with eyes, shin and dothing. Wash thoroughly after handling

First Aids: If swallowed, do not induce vomiting Call a physician immediately IF you experience difficulty in breathing, leare the area to obtain firsh air. If continued difficulty is experienced, get medical assistance immediately. In case of eje contact, flush immediately with plenty of water for at least 15 minutes and get medical attention, for skin, wash thoroughly with scap and water. If spilled, containing and cremove with increase and eje contact, flush immediately being of water for at least 15 minutes and get medical attention, for skin, wash thoroughly with scap and water. If spilled, containing and cremove with increase that and forced regulations.

KEEP OUT OF REACH OF CHILDREN.

11/08

