

CL

Dashed line does not print. Represents maximum print area.



0 79941 00917 5

UGL®

DRYLOK®

FAST PLUG®

HYDRAULIC CEMENT

Seals open joints and cracks in masonry and concrete

Stops active water leaks

FAST SETTING **3-5 MINUTES**

WARNING! INJURIOUS TO EYES. Harmful if inhaled. CAUSES SKIN IRRITATION/BURNS. Contains Portland Cement and lime. **4 LBS. (1.8 kg)**

■ Interior/Exterior

■ Reduces radon gas penetration

Center
Front

1/8" ■ **WARNING!**
3/32" ■ **INJURIOUS**
5/64" ■ **Cancer**

CL

Center
Back

DRYLOK® FAST PLUG® is a powder formula, when mixed with water, sets in 3-5 minutes. Ideal for sealing floor and wall joints, settlement cracks, and permanently anchoring metal to masonry.

DIRECTIONS

1. Prepare the Surface: Clean thoroughly by wire brushing, scraping, or chiseling until loose, crumbling masonry is removed and a sound surface remains. Cracks should be chiseled out to the shape of an inverted "V."
Important: Wear eye protection, a dust mask, and rubber gloves.

2. Mix: Mixing Ratio-3:1. Mix only enough for immediate use. Mix 1-part cold water to 3 parts of DRYLOK® Fast Plug® and mix to a heavy consistency. For a slower setting time, use colder water.

3. Apply: Inactive leaks or routine patching: Soak the area to be patched with water. This prevents the masonry surface from drawing moisture out of the DRYLOK® Fast Plug® and creates a stronger patch area. Apply DRYLOK® Fast Plug® with a trowel or putty knife, forcing the patch into the affected area. Smooth the patch.

Active leaks, where water is flowing through a break in the surface: Mix and wait 1 minute or until the mixture becomes warm to the touch. Force the DRYLOK® Fast Plug® into the opening and hold in place for 3-5 minutes. Smooth the patch.

Coverage: Each 4 lbs. will fill up to 64 cubic inches. **Clean up:** Soap and water.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

UNITED GILSONITE LABORATORIES, 1396 Jefferson Ave., Dunmore, PA 18509

ORDER NO. 00917

UFI : 1UX5-18A9-A00M-JM38

www.DRYLOK.com

Made in USA

LR622




Cancer hazard: Contains Crystalline Silica which can cause cancer. (Risk of cancer depends on duration and level of exposure.)

Use only with adequate ventilation. Do not breathe dust. Harmful if inhaled. Overexposure may cause lung and kidney damage. Avoid contact or prolonged contact with eyes, skin, and clothing. Ensure fresh air entry during application and drying. If you experience eye watering, headache, or dizziness, or if air monitoring demonstrates vapor levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH approved) during and after application. Follow respirator manufacturer's directions for respirator use. Close container after each use. Wash thoroughly after handling.

First Aid: If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, call poison control center, hospital emergency room, or physician immediately. In case of contact, immediately flush skin with soap and plenty of water. In case of eye contact, flush with plenty of water for at least 15 minutes. Consult a physician immediately.

KEEP OUT OF REACH OF CHILDREN

 **WARNING:** Cancer and Reproductive Harm-
www.P65Warnings.ca.gov.



NO PRINT - GAP AREA