

**IDEAL INDUSTRIES, INC.**

Sycamore, IL 60178 U.S.A.
800-435-0705 • www.idealind.com

IS 0003-1 Made in Taiwan / Hecho en Taiwán / Fabriqué à Taiwan

**Drill Tap Use & Care Guide****36-600****DO NOT ROCK**

For optimal performance:

- Keep drill tap bit perpendicular to work surface.
- Do not slow bit when approaching the threading step. Use full recommended RPM throughout the initial cut.
- To remove the bit, put the drill in reverse, pull the drill tap up so that the threads are engaged with the bottom of the hole. Then, slowly reverse the bit through the hole, making sure to keep the bit vertical.
- Use with cordless or impact rated drills.
- Use a fully charged battery.
- Use the recommended RPM range of 300 to 1,500 RPM.

⚠ WARNING **Electrical and eye injury hazard.** Contact with live voltage may cause injury or death. Do not use on near or on live voltage. Wear eye protection.



WARRANTY: See www.idealind.com or call Customer Assistance for warranty details.

SPANISH

For optimal performance:

- Keep drill tap bit perpendicular to work surface.
- Do not slow bit when approaching the threading step. Use full recommended RPM throughout the initial cut.
- To remove the bit, put the drill in reverse, pull the drill tap up so that the threads are engaged with the bottom of the hole. Then, slowly reverse the bit through the hole, making sure to keep the bit vertical.
- Use with cordless or impact rated drills.
- Use a fully charged battery.
- Use the recommended RPM range of 300 to 1,500 RPM.

⚠ AVERTISSEMENT **Riesgo de electrocución y de lesión de los ojos.**

El contacto con la línea de alta tensión puede causar lesiones o la muerte. No utilice cerca o en tensión viva. Use gafas de seguridad.



GARANTÍA: Visite www.idealind.com, o llame al Servicio al Cliente para los detalles de la garantía.

FRENCH

For optimal performance:

- Keep drill tap bit perpendicular to work surface.
- Do not slow bit when approaching the threading step. Use full recommended RPM throughout the initial cut.
- To remove the bit, put the drill in reverse, pull the drill tap up so that the threads are engaged with the bottom of the hole. Then, slowly reverse the bit through the hole, making sure to keep the bit vertical.
- Use with cordless or impact rated drills.
- Use a fully charged battery.
- Use the recommended RPM range of 300 to 1,500 RPM.

⚠ AVERTENCIA **Riesgo de electrocución y de lesión de los ojos.**

El contacto con la línea de alta tensión puede causar lesiones o la muerte. No utilice cerca o en tensión viva. Use gafas de seguridad.



GARANTÍA: Visite www.idealind.com, o llame a Asistencia al Cliente para los detalles sobre la garantía.