USER MANUAL

XP990

Ultra-range 1500L Focus

USB
Rechargeable



FEATURES

- TACKGRIP®
- USB-C Charge Cable
- LPE Optics
- Power Bank
- 700 Meter Throw

ANSI/PLATO FL1 STANDARD			
MODES	**LUMENS**	**RUN TIME**	**BEAM DISTANCE**
High	1500/1507	2H 30M	703
Medium	803 lm	5H 30M	541
Low	256 lm	11H 45M	347

OPERATION INSTRUCTIONS

On/Off: Press and release on/off button.

Cycle Modes: Easily cycle through modes by pressing the power button within 8 seconds of turning the flashlight on. After 8 seconds of inactivity, the next button press will turn the light off.

Press button to activate battery indicator. Blue LED 50% or more, Red LED 30%-50% power, Red Flashing LED less than 30% power. The battery indicator will automatically turn off.

CHARGING INSTRUCTIONS

Charging Instructions: To charge the flashlight, open the charging port cover located on the side opposite the power button. Insert the USB-C end of the charging cable into the port, then connect the other end to a 5V power source. Red = Charging. Blue = Fully Charged

The XP990 has a charge time of approximately 3 hours.



PRODUCT WARRANTY

The XP990 has a Limited Lifetime Warranty Against Manufacturer's Defects from time of purchase.
For warranty claims please contact us by calling 801-553-8886 or sending an email to info@luxpro.com

14725 S Porter Rockwell Blvd Ste C
Bluffdale, UT 84065