
















Assembly instruction B (T/ TXL)










Assembly instruction B (T/ TXL)



① x1 	② x3 	③ x1 
②④ x4 	⑤ x8 	②⑥ x4 
⑦ x9 	⑧ x4 	⑩ x2 
②② x28 	②③ x2 	①④ x1 
①⑦ x2 	①⑧ x4 	①⑨ x1 
②⑩ x4 		

Hardware List

A×32 (2+extra)  M8×20mm	B×17(1+extra)  M6×55mm	C×4  M6×40mm
D×15 (5+extra)  M6×32mm	E×26 (1+extra)  M6×15mm	F×49 (4+extra)  M6×10mm
G×8 (1+extra)  M6×15mm	H×2  M4	I×2 
J×2  M8×40mm	K×2  M5×40mm	


1

F×32pcs





M6×10mm


Step 1



Step 2




2



E×8pcs




M6×15mm




3



A×8pcs



M8×20mm




x 2

4




B×4pcs




M6×55mm

D×4pcs



M6×32mm




x 2

5


F×8pcs




M6×10mm




6




A×4pcs



M8×20mm




7




E×4pcs




M6×15mm




8




A×4pcs




M8×20mm




9




C×2pcs



M6×40mm



10



B×1pc





M6×55mm

E×2pcs




M6×15mm



11




B×1pc




M6×55mm


D×1pc



M6×32mm





12




Tighten all screws 100%

13



D×4pcs



M6×32mm

E×4pcs





M6×15mm

G×4pcs



M6×15mm


14



A×8pcs




M8×20mm




x 2

15




B×4pcs




M6×55mm

D×4pcs




M6×32mm



x 2


16




A×4pcs



M8×20mm




17




A×4pcs




M8×20mm




18




C×2pcs



M6×40mm



19



Tighten all screws 100%