




①



②



③












④

Do not apply soldering iron to terminals for longer than 5 seconds

Ne pas appliquer fer à souder aux terminaux pour plus de 5 secondes

Nicht anwendbar lötkolben zu Terminals für länger als 5 Sekunden

No se aplicará hierro de soldar a las terminales durante más de 5 segundos







**Caframo**

Caframo Limited  
501273 Grey Road 1  
Georgian Bluffs, ON  
N0H 2T0  
Canada

Toll Free / Sans Frais : 1-800-567-3556  
Tel / Tél : 1-519-534-1080  
www.caframo.com

MRKMN002 Rev01

**Caframo**

Motor Replacement Instructions  
for Ecofan and Alcona

Instructions pour kit de rechange  
de moteur pour Ecofan et Alcona



Model  
800CA


















Model  
802CA



Model  
T805

Model / Modèle  
800CA 802CA T805



Do not apply soldering iron  
to terminals for longer than 5  
seconds

Ne pas appliquer fer à souder  
aux terminaux pour plus de 5  
secondes

Nicht anwendbar lötkolben  
zu Terminals für länger als 5  
Sekunden

No se aplicará hierro de soldar  
a las terminales durante más de  
5 segundos