USER MANUAL

XP782

Power 3000L Headlamp

USB
Rechargeable



FEATURES

- Removable over-the-head strap
- 42hr Max Runtime
- Super Strong Magnetic Side
- Turbo Mode

ANSI/PLATO FL1 STANDARD

MODES	LUMENS	RUN TIME	BEAM DISTANCE
Turbo	3000 lm	30s	160
High	1000 lm	2H	90
Medium	400 lm	4H	61
Low	25 lm	42H	13

OPERATION INSTRUCTIONS

On/Off & Cycle Modes: Press button to turn on. Within 3 seconds, press the button to cycle through modes

Turbo: Press and hold button for 3 seconds

Smart Button: Green = over 25%, Red = low battery

CHARGING INSTRUCTIONS

Charging Instructions: To charge the headlamp, locate the USB port the front of the headlamp near the button. Rotate the charge port cover to access the charging port. Plug the small end of the included charging cable into the headlamp and the opposite end into a 5V power source.

The XP782 has a charge time of approximately 3 hours.

PRODUCT WARRANTY

The XP782 has a Limited Lifetime Warranty Against Manufacturer's Defects from time of purchase.
For warranty claims please contact us by calling 801-553-8886 or sending an email to info@luxpro.com

14725 S Porter Rockwell Blvd Ste C
Bluffdale, UT 84065