

## Sweat Solder Kits



### SWEAT SOLDER KITS

Item No.	Code No.	Part No.	Description
<b>H-533-A</b>			
1	<b>3308603</b>	H-532	1" Adapter*
1, 2, 5	<b>3308780</b>	H-533-AS	Sweat Solder Kit W/Stamped Wall Flange for 1" Supply-Closet & Urinal
1-4	<b>3308794</b>	H-533-AC	Sweat Solder Kit W/Cast Wall Flange for 1" Supply-Closet & Urinal
2	—	H-534	Casing Tube for 1" Copper
<b>H-534-A</b>			
1	<b>3308603</b>	H-532	1" Adapter*
1, 2, 5	<b>3308783</b>	H-534-AS	Sweat Solder Kit W/Stamped Wall Flange for 1" Supply-Closet & Urinal
1-4	<b>3308796</b>	H-534-AC	Sweat Solder Kit W/Cast Wall Flange for 1" Supply-Closet & Urinal
2	—	H-534	Casing Tube for 1" Copper
<b>H-536-A</b>			
1	<b>3308607</b>	H-535-A	3/4" Adapter*
1, 2, 5	<b>3308786</b>	H-536-AS	Sweat Solder Kit W/Stamped Wall Flange for 3/4" Supply-Closet & Urinal
1-4	<b>3308798</b>	H-536-AC	Sweat Solder Kit W/Cast Wall Flange for 3/4" Supply-Closet & Urinal
2	—	H-537	Casing Tube for 3/4" Copper

Note: H-532-AS, H-533-AS, H-534-AS, H-535-AS and H-536-AS are also identified as suffix YB when furnished with flush valve.

\*Furnished separate for concealed installations.

Item No.	Code No.	Part No.	Description
<b>H-633-AA</b>			
1	<b>3308603</b>	H-532	1" Adapter
1-4	<b>3308782</b>	H-633-AA	Sweat Solder Kit for 1" Supply – Urinal 3" Tube
2	—	H-534	Casing Tube for 1" Copper
<b>H-634-AA</b>			
1	<b>3308603</b>	H-532	1" Adapter
1-4	<b>3308785</b>	H-634-AA	Sweat Solder Kit for 1" Supply – Closet 6" Tube
2	—	H-534	Casing Tube for 1" Copper
<b>H-636-AA</b>			
1	<b>0308607</b>	H-535	3/4" Adapter
1-4	<b>3308788</b>	H-636-AA	Sweat Solder Kit for 3/4" Supply – Urinal
2	—	H-537	Casing Tube for 3/4" Copper



**Showerheads,  
Parts and  
Accessories**