



ASSEMBLY INSTRUCTION (WF309334 / WF309335)




ASSEMBLY INSTRUCTION (WF309334 / WF309335)




Part List (Box 1 - WF309334)

1




Headboard 1 pc

2



Footboard 1 pc


3



LVL Slats 12 pcs


Part List (Box 2 - WF309335)

4




SidePanel (L) 1 pc

5




SidePanel (R) 1 pc

6




Center Wood 1 pc

7




Center Legs 4 pcs

8



Headboard Leg (L) 1 pc

9




Headboard Leg (R) 1 pc

10



Footboard Legs 2 pcs


11



CASTER
NO LOCK 8 PCS


Part List (Box 2 - WF309335)

12

A 3D line drawing of a long, thin rectangular headboard piece, oriented diagonally.


Trundle Bed Headboard 1pc

13

A 3D line drawing of a long, thin rectangular footboard piece, oriented diagonally.


Trundle Bed Footboard 1pc

14

A 3D line drawing of a long, thin rectangular side panel piece with a small notch on one end, oriented diagonally.


Trundle Bed SidePanel (L) 1pc

15

A 3D line drawing of a long, thin rectangular side panel piece, oriented diagonally.

Trundle Bed SidePanel (R) 1pc


16

A 3D line drawing showing 12 parallel slats arranged in two rows of six, oriented diagonally.


Trundle Bed LVL Slats 12pcs

Hardware List (Box 1 - WF309334)

H











USB 2 pcs



ASSEMBLY TOOLS REQUIRED (NOT INCLUDED)


Hardware List (Box 2 - WF309335)

A  M4 X 16 MM Chipboard Screw 32pcs	B  M4 X 32 MM Chipboard Screw 48 pcs	C  M4 X 45 MM Chipboard Screw 2 pcs
D  M6 X 30 MM JCBC Screw 8 pcs	E  M6 X 45 MM JCBC Screw 10 pcs	F  M4 Allen Key 1 pc
G  M5 Allen Key 1 pc		




ASSEMBLY TOOLS REQUIRED (NOT INCLUDED)

ASSEMBLY INSTRUCTION (WF309334 / WF309335)




ASSEMBLY INSTRUCTION


STEP 1




STEP 2



STEP 3





STEP 4





ASSEMBLY INSTRUCTION

STEP 5




STEP 6




12 PCS
LVL SLATS

3





COMPLETE





ASSEMBLY INSTRUCTION



STEP 7




STEP 8



STEP 9



COMPLETE



FULLY COMPLETED ASSEMBLY

