



PROBLEM	SUGGESTION
1	Fix the hanging plate on the ceiling with screws
2	Fix the top box on fan the body with screws
3	Connect all wires and insulate them with the wiring diagram of remote controller
4	Fix the machine head on the hanging plate
5	Install the blades on the motor(Note:The screwdriver cannot be inserted into the motor holes to arrange the blades, which causes the motor wire to short)
6	Fix the lamp on the iron base
7	Connect the light wires L/N according to the color and insulate it
8	Cover the lampshade

Safe note Cut off the power before installing the fan lamp