



DJYC2605


ASSEMBLY INTRODUCTION



Exploded View




Fitting




Ax35(+2)
Ø6x35mm



Bx35(+2)
Ø15x10mm




Cx41(+2)
Ø6x30mm



Dx7(+1)
Ø4x35mm



Ex48(+2)
Ø3.5x12mm



Fx6(+1)
Ø4x50mm



Gx8



Hx8




Ix4




Jx4



Kx16(+1)
Ø3x16mm




Lx2
Ø4x14mm




Mx2
Ø6x30mm


Step 1




Step 2



Step 3





Bx8




Cx4

Step 4




Ax4

Step 5





Bx8





Cx2

Step 6





Cx10


Step 7




Step 8




Step 9




Step 10



Step 11





Step 12




Cx10

Step 13





Ax6



Step 14





Step 15





Step 16





Step 17






Step 18



Step 19



Step 20



Step 21

