
WM-5G



INSTALLATION INSTRUCTIONS


Step 1: Drill holes for the desired location.

Determine your desired location for installation and make a mark for the location. Make 2 marks where mounting screws will be placed as shown below. Drill hole at each of the marks.



Step 2: MOUNTING

Mount Assembly to desired location through screws provided.



No portion of this document or any artwork contained herein should reproduced in any way without the written conset of ALLIED BRASS INC.