


Overbed Table

Instruction Manual

D-CXZ01-BN

D-CXZ01-WT



1 Component List

A X1






Table Board

B X1



Column


C X1



Bottom Bracket

2 Supplied Parts and Hardware

1 X9





Screw
M6*16

2 X1




Wrench

Step 1



Use Wrench ② and Screws ①*4 to connect Column B and Table Board A.

Step 2



Use Wrench ② and Screws ①*4 to connect Column B and Bottom Bracket C.

Step 3




Table height can be adjusted by adjusting the lift handle.

NOTE : Maximum load capacity is 22.05 lbs.

