

Handling Precautions

Wear dust mask, goggles, and gloves when cutting, drilling, sanding, or handling. After working, wash exposed skin thoroughly and wash work clothes separately from other clothing. Do not burn treated wood. Do not use treated wood where it could come into direct or indirect contact with drinking water or human/animal food, such as cutting boards, counters, food storage containers, beehives, animal bedding or mulch. Use hot dipped galvanized (ASTM A 153 & G 185) or stainless steel (304 or 316) Connectors and Fasteners. Do not use in direct contact with aluminum.