



















Assembly Instruction




NO.	QTY.	LINEDRAWING
(A)	30	
(B)	30	
(C)	36	
(D)	2	
(E)	4	
(F)	4	
(G)	8	
(H)	30	
(I)	20	 5*20
(J)	48	 4*14
(K)	10	
(L)	12	 3*16
(M)	8	 4*35
(N)	4	
(O)	1	
(P)	8	 3*12

PARTS LIST





NO.	QTY.	NO.	QTY.
①	1	⑥	1
②	1	⑦	1
③	1	⑧	1
④	1	⑨	4
⑤	1	⑩	2



⑪	2
⑫	1
⑬	1
⑭	2
⑮	2
⑯	2
⑰	2





1





2




3




4



5




6




C		8x
A		8x
B		8x

7







C		2x
A		4x
B		4x

8






C		2x
A		4x
B		4x



9





10




11





12








13



 G	 J
8x	16x

14



 J	 E	 F	 D
32x	4x	4x	2x

15

