## **CARE AND MAINTENANCE**

Wipe clean with a soft, dry cloth. Test the cleaning method on a hidden area before using them over the entire area.

## NOTICE

- \* Please make sure that you have all parts indicated before you begin assembly of this item.
- \* This item should be assembled on a soft surface to prevent scratching the finished product during assembly.
- \* This item may require periodic tightening.
- \* Do not tighten bolts until completely assembled.




Model# COF6207

Product Dimensions: \$\phi 36-1/4\text{"} x 18\text{"H}

## **Part List and Hardware List**

PIECE	DESCRIPTION	PICTURE	QUANTITY
A	Table top		1x
В	L type side frame		2x
С	U type side frame		1x
HW1	Hex Socket Bolt	6))))))) 1/4"-20x5/8"	13x
HW2	Metal plate	3.0x45x120mm	1x
HW3	Allen Key	M4	1x






Weight capacity:25lbs
WARNING:DO NOT STAND ON TABLE
WARNING:DO NOT OVER TORQUE BOLTS


## **PREPARATION**


Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list. If any part is missing or damaged, do not attempt to assemble the product.

Estimated Assembly Time: 15 minutes.

Tools Required for Assembly (included): Allen Key







Step 1

Attach 1\*U type Side Frame (C) & 2\*L type Side Frames (B) together with Metal Plate (HW2), Use Allen key (HW3) to lock through holes on Metal Plate with 5\*Hex Socket Bolt (HW1).

Step 2

Attach the assembled metal base (as step 1) with the bottom side of Table top (A) and aligning, Use Allen Key (HW3) to lock 8\*Hex Socket Bolts (HW1), as picture.

Step 3

Straighten up the assembled product, Assembly is completed.