CARE AND MAINTENANCE

Always use felt pads under all articles to prevent discoloration or softening of the lacquer. Plastic and rubber bases on items can discolor wood. Wipe up spill immediately and avoid common hazards such as hot dishes,harsh solvents and abrasives. Cleaning should be done with a soft lint free cotton cloth dampened with water or furniture polish. On highly used surfaces we recommend applying a quality paste wax which should be used on a regular basis to provide additional protection from sratches and spills. How often you apply the wax depends on how much wear the furniture receives.

NOTICE

* Please make sure that you have all parts indicated before you begin assembly this item.

* This item should be assembled on a soft surface to prevent scratching the finish during assembly.

- * This item may require periodic tightening.
- * Requiring atleast two person to assemble the product

Part List and Hardware List

PIECE	DESCRIPTION	PICTURE	QUANTITY
А	Table Top		1x
В	Leg		4x
С	Cross Rail Up/Down	· •• · · · · · •• · ·	2x
D	Pedestal		1x
E	Pedestal Cap		1x
HW 1	Csk Screw M4x2.0x30mm		16x
HW 2	Nut 13mmØ		8x
HW 3	Spring Washer 8mm $oldsymbol{arnothing}$		8x
HW 4	Flat Washer 8 mm $Ø$	\bigcirc	8x
HW 5	Jcbc Bolt M8x0.5x60mm		8x
HW 6	Allen Key M5		1x
HW 7	Spanner 13mm		1x

SAFAVIEH

Item Id : DTB 1405

Product Dimensions : 47.24" W x 47.24" D x 29.92" H



Weight Capacity : 165 lbs

WARNING : DO NOT OVER TORQUE BOLTS/SCREWS



PREPARATION

Before beginning assembly of product, make sure all parts are present. Compare parts with package content list. If any part is missing or damaged, do not attempt to assemble the product. Estimated Assembly Time : 20 minutes.







Step 2 Assemble the cross rail then tight it.

PREPARATION

Before beginning assembly of product, make sure all parts are present. Compare parts with package content list. If any part is missing or damaged, do not attempt to assemble the product. Estimated Assembly Time : 20 minutes.



Step 3

Put upside down the table top, then tight the leg frame. Make sure put on the smooth and clear surface, to avoid the surface scratch.



