



ASSEMBLY INSTRUCTION


MF323325

If you have any questions, please feel free to contact us.
Email: lowes.team@qualfurn.net












Minimum no. 2 of people
recommended to assemble
this product: Approx.
assembly time: 60 mins










PART LIST MF323325

1		1PC	2		1PC	3		1PC
4		1PC	5		2PCS	6		1PC
7		1PC	8		1PC	9		1PC
10		1PC	11		6PCS	12		15PCS
13		1PC	14		1PC	15		1PC

HARDWARE LIST MF323325




A		M $\frac{1}{4}$ "X50 43 PCS	B		M $\frac{1}{4}$ "X35 12 PCS	C		M $\frac{1}{4}$ "X15 15 PCS	D		5PCS Ø38x20	E		1PC Ø32x20
F		20PCS M4x15	G		M4X23X57 1PC									

PART LIST MF323325

16		17		18	
	1PC		2PCS		1PC
19		20		21	
	1PC		2PCS		2PCS
22		23		24	
	1PC		2PCS		2PCS
25		26			
	1PC		1PC		




STEP 1

A	D
 M $\frac{1}{4}$ "x50	 Ø38x20
3 PCS	2 PCS



STEP 2



A	D
 M $\frac{1}{4}$ "x50	 Ø38x20
8 PCS	2 PCS



STEP 3

F



M4x15
10PCS



STEP 4

F

M4x15
10PCS





STEP 5

C

M $\frac{1}{4}$ "x15

12 PCS





60%

STEP 6

C

M $\frac{1}{4}$ "x15

3 PCS





60%

STEP 7




A

M $\frac{1}{4}$ "x50
12 PCS






STEP 8

A	D
 M $\frac{1}{4}$ "x50	 Ø38x20
4 PCS	1 PC




STEP 9

A	E
	
M $\frac{1}{4}$ "x50	Ø32x20
4 PCS	1 PC




STEP 10




A	B
	
M $\frac{1}{4}$ 'x50	M $\frac{1}{4}$ 'x35
4 PCS	2 PCS

STEP 11





B

M $\frac{1}{4}$ 'x35
2 PCS





STEP 12

A	B
 M $\frac{1}{4}$ "x50	 M $\frac{1}{4}$ "x35
4 PCS	4 PCS



STEP 13

A	B
	
M $\frac{1}{4}$ "x50	M $\frac{1}{4}$ "x35
4 PCS	4 PCS



STEP 14

