



Please slowly tear off the protective plastic film on the surface along the edge. After peeling off, the product becomes smooth and clean.




A*8
B * 3

put A on board (5) put B on board 56








X C*6 D*3 E*3 F*1 **LED**

put C on board (1)(4)put D on board (3) put E on board (3) put F on board (3)



Make sure the arrow on the screw align to the hole on the side.

5 put G on board 1246 G*18