



Work bench with one drawer



1




- 1) M6x16 mm (x4)
2) M6x12 mm (x10)
3) M6x10 mm (x6)
4) M6x10 mm (x6)
5) 1/4" (x4)
6) M6 (x7)
7) M6 (x18)
8) M6 (x7)
9) M6 (x18)
10) (x12)
11) (x1)
12) (x2)
13) (x4)
14) (x2)
15) (x2)
16) (x1)
17) (x1)
18) (x1)
19) (x3)
20) (x4)
21) 500 mm (x2)
22) 996 mm (x2)
23) (x1)
24) (x1)
25) (x1)
26) (x1)
27) (x1)
28) (x1)


2



- A(x1) B(x1) C(x1) D(x1) E(x1)




3




- 21) 500 mm (x2)
22) 996 mm (x2)
23) (x1)
24) (x1)
25) (x1)
26) (x1)
27) (x1)
28) (x1)


4




5




6




7




8



9



10



11