

#31-148




Fish Tape Leader

- *Maneuvers around bends*
- *500 lb pull strength*



Made in U.S.A. of
U.S. and Global
Components



Fish Tape Leader

- Flexes in all directions
- Guides fish tape through bends and obstructions
- Brass-plated to resist corrosion
- 500 lb. pull strength

For Use With

- .060" x .125" steel fish tape

Caution

Do not exceed 500 lb. pull.

Follow safeguards and instructions furnished with the fish tape.

Precaución


No exceda el límite de tracción de 220 N (500 lb.).

Siga las precauciones e instrucciones que vienen con la cinta pasacables.

Instructions

Instrucciones

1. Unscrew end-cap from leader.



2. After cutting off loop on fish tape, slide fish tape through hole in adapter.

1. Desatornille la tapa del extremo del guiador.

2. Después de cortar el anillo de la cinta pasacables, deslice la misma por el orificio del adaptador.



3. Heat end of fish tape to a dull red and bend end with pliers. Flatten end of tape while still dull red. Reheat if necessary.

4. Allow tape to cool. Do not quench.

3. Caliente el extremo de la cinta pasacables hasta que adquiera un color rojo mate y doble el extremo con unos alicates. Aplaste el extremo de la cinta mientras ésta tenga todavía un color rojo mate. Vuelva a calentar si es necesario.

4. Deje que la cinta se enfríe por sí sola. No la enfríe con agua.

5. Reattach adapter to leader and tighten. Pull on fish tape to ensure secure connection.

5. Vuelva a montar el adaptador al guiador y apriételo. Tire de la cinta pasacables para asegurarse de que quede bien sujetada al adaptador.

Warranty limited solely to repair or replacement; no warranty of merchantability, fitness for a particular purpose or consequential damages.

IDEAL INDUSTRIES, INC.


Sycamore, IL 60178, U.S.A.

800-435-0705 Customer Assistance

www.idealindustries.com

ND 049-4

Made in U.S.A. of US and global components.



7 83250 31148 4