7.87 inch / 200 mm **WARNING:** Protect yourself and others. Read and understand this label and the appropriate Material Safety Data Sheet (MSDS) die sure that both the label and the MSDS are read by the velder (end uses). FUMES AND OAGES can be despression to MSD (MSDS) and MSDS (MSDS) are read by the velder (end uses). FUMES AND OAGES can be despression to MSDS (MSDS) and MSDS (MSDS) are read by the MSDS (MSDS) and MSDS (MSDS) and MSDS (MSDS) are strengthed to the manufacturer's instructions and your safety practices. Keep your head out of the tumes. Use recovery entitlation andor exhaust at the are to keep fumes and SIZE: 0.03"/0.8mm your safety practices. Keep your head out of the fumes. Use enough entilation and/or exhaust at the act to keep fumes and gases from your breathing zone and below permissible exposure limits. Take special care when welding on coated metals, such as painted, galvanized, or plated parts. To avoid exposure to toxic fumes. Proper use of appropriate respirator is essential if ventilation is adequate. See Sanven Technology Ltd. .87 sential if ventilation is adequate. See references below: Wear correct eye, ear, and body protection. Do not touch live electrical parts. This product may contain detectable quantities of chemicals listed in appl -icable state regulations as causing caneer, birth defects, or other reprodu-ctive harm. inch SN: 20230601751020264 Do Not Remove, Cover or Destroy This Warning. 200 mm