



#33-620

Basic Compression Starter Kit

Includes:

LinearX3™ Adjustable Compression Tool for F/BNC/RCA
PrepPRO™ Coax Stripper for 6/6Q/59 cables
Data T®-Cutter
(30) RTQ™ RG-6/6Q WeatherProof F-Compression Connectors
(10) RTQ™ RG-59/59Q WeatherProof F-Compression Connectors

Instructions:

- Place cable into coax stripper with end of cable flush against gray wall.
- Rotate stripper 3-4 times around cable.
- Remove stripped sections, leaving a 1/4 in. x 1/4 in. cable preparation. 1/4 in. of center pin will be exposed and 1/4 in. of braiding will be exposed.
- Fold back cable braiding against cable jacket.
- Push connector on to cable until white dielectric is flush with the bottom of the connector nut.
- Place assembly in compression tool and squeeze handle closed.

Note: LinearX3™ tool post can be adjusted up or down for compression connectors of different lengths and types, such as BNC or RCA connectors.

IDEAL INDUSTRIES, INC.

Sycamore, IL 60178, U.S.A.
800-435-0705 Customer Assistance
www.idealindustries.com
ND 7915-1
