CABINET USE & CARE



WOOD



CERAMIC

Spray with mild, soapy solution or water and vinegar mixture. Wipe immediately with a clean rag to remove the soap residue. Do not let water sit on the hardware.

Rub with a damp rag or cloth.



Wipe clean with rag or cloth.



GLASS

Spray with glass cleaner or water and vinegar solution.



METAL

Spray with mild, soapy solution or water and vinegar mixture. Wipe with a clean rag to remove the soap residue.

Alternate method: Remove hardware using a screw driver. Soak in a soapy solution for several hours or overnight. Rinse and thoroughly dry prior to installation.