

# **WARNING!** COMBUSTIBLE LIQUID AND VAPOR.

See Other Cautions On Back Panel.

LEAD FREE

Contains: NAME LONG OIL ALKYD RESIN TITANIUM DIOXIDE AROMATIC PETROLEUMS HYDROCARBONS

Proprietary Proprietary 13463-67-7 37244-96-5 64742-95-6



# **DURALUX® NAVY GRAY**

M723

ONE GALLON U. S. STANDARD MEASURE

## **Basic Use And Information**

Duralux is the highest quality marine enamel available. The white stays white and colors bright and clear. It is made from alkyd resin for smoother leveling. It resists oil, gasoline and discoloration from harbor gases.

#### **Technical Information**

**Distance:** On properly prepared surfaces, expect to cover from 400-500 square feet per gallon.

Drying Time: Four hours, but slightly longer on damp or cold days. Allow 12-16 hours for hardening before repainting

Maximum V.O.C.: 3.8 lbs./gal.

### **Surface Preparation**

The surface must be dry and free of grease, wax, dirt, or other foreign matter. Scrape off all loose paint and dull any gloss with a light sanding or power brushing. Remove all dust with a clean cloth dampened with paint thinner and allow to dry. WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPO-SURE TO LEAD DUST CAN CAUSÉ SERIOUS ILLNESS, SUĆH AS BRAIN DÁMAGE, ÉSPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead. Unpainted Surfaces:

- Wood Prime with Duralux Yacht Primer No. M741, apply two coats of Duralux.
  Steel: On clean, rust-free steel, apply two coats of Duralux Zinc Chromate Primer No. M739, apply two coats of Duralux.
- Aluminum: Pretreat with suitable wash primer. Apply one coat of Duralux Zinc Chromate Primer No. M739. Top with two full coats of Duralux.
- Fiber Glass: Top with two thin coats of Duralux.

#### Painted Surfaces:

- Wood Sand thoroughly, spot prime bare areas then apply two coats of Duralux.
- Steel Clean all bare areas to bright steel. Touch up with two coats of Duralux Zinc Chromate Primer No. M739. Top with two full coats of Duralux.
- Aluminum Touch up all bare areas with Duralux Zinc Chromate Primer No. M739. Top with two full coats of Duralux
- Fiber Glass Sand surface until dull finish is obtained. Top with two thin coats of Duralux

### Application

- Method: Use brush, spray or roller.
- Thinning: Not recommended. If thinning is desired, use either Paint Thinner 650 or xylene up to a half-pint per gallon.
- Clean Up: Clean equipment with paint thinner.

#### **CONTAINS PETROLEUM DISTILLATE**

VAPOR HARMFUL. MAY AFFECT THE BRAIN OR NERVOUS SYSTEM CAUSING DIZZINESS, HEADACHE OR NAUSEA. CAUSES EYE, SKIN, NOSE AND THROAT IRRITATION. NOTICE: Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents may be harmful or fatal.

Keep away from heat and flame. Do not smoke. Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. Do not breathe vapors or

Use only with adequate ventilation. Ensure fresh air entry during application and drying. If you experience eye watering, headache or dizziness or if air monitoring demonstrates vapor/mist levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH/MSHA approved) during and after application. Follow respirator manufacturer's directions for respirator use. Close container after each use. Avoid contact with eyes, skin and clothing. Wash thoroughly after handling. First Aid: If swallowed, do not induce vomiting. Call a physician immediately. If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical assistance immediately. In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attendance. tion; for skin, wash thoroughly with soap and water.

If spilled, contain spilled material and remove with inert absorbent. Dispose of contaminated absorbent, container and unused contents in accordance with local, state and federal regulations.

KEEP OUT OF REACH OF CHILDREN.



▲ WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov