



# ASSEMBLY INSTRUCTION


MF323325

If you have any questions, please feel free to contact us.  
Email: [lowes.team@qualfurn.net](mailto:lowes.team@qualfurn.net)












Minimum no. 2 of people  
recommended to assemble  
this product: Approx.  
assembly time: 60 mins










# PART LIST MF323325

|    |                                                                                     |     |    |                                                                                     |      |    |                                                                                       |       |
|----|-------------------------------------------------------------------------------------|-----|----|-------------------------------------------------------------------------------------|------|----|---------------------------------------------------------------------------------------|-------|
| 1  |    | 1PC | 2  |    | 1PC  | 3  |    | 1PC   |
| 4  |    | 1PC | 5  |    | 2PCS | 6  |    | 1PC   |
| 7  |    | 1PC | 8  |   | 1PC  | 9  |   | 1PC   |
| 10 |  | 1PC | 11 |  | 6PCS | 12 |  | 15PCS |
| 13 |  | 1PC | 14 |  | 1PC  | 15 |  | 1PC   |

# HARDWARE LIST MF323325




|   |                                                                                     |                                |   |                                                                                     |                                |   |                                                                                     |                                |   |                                                                                       |                |   |                                                                                       |               |
|---|-------------------------------------------------------------------------------------|--------------------------------|---|-------------------------------------------------------------------------------------|--------------------------------|---|-------------------------------------------------------------------------------------|--------------------------------|---|---------------------------------------------------------------------------------------|----------------|---|---------------------------------------------------------------------------------------|---------------|
| A |  | M $\frac{1}{4}$ "X50<br>43 PCS | B |  | M $\frac{1}{4}$ "X35<br>12 PCS | C |  | M $\frac{1}{4}$ "X15<br>15 PCS | D |  | 5PCS<br>Ø38x20 | E |  | 1PC<br>Ø32x20 |
| F |  | 20PCS<br>M4x15                 | G |  | M4X23X57<br>1PC                |   |                                                                                     |                                |   |                                                                                       |                |   |                                                                                       |               |

PART LIST MF323325

|    |                                                                                     |    |                                                                                     |    |                                                                                       |
|----|-------------------------------------------------------------------------------------|----|-------------------------------------------------------------------------------------|----|---------------------------------------------------------------------------------------|
| 16 |    | 17 |    | 18 |    |
|    | 1PC                                                                                 |    | 2PCS                                                                                |    | 1PC                                                                                   |
| 19 |    | 20 |    | 21 |    |
|    | 1PC                                                                                 |    | 2PCS                                                                                |    | 2PCS                                                                                  |
| 22 |  | 23 |  | 24 |  |
|    | 1PC                                                                                 |    | 2PCS                                                                                |    | 2PCS                                                                                  |
| 25 |  | 26 |  |    |                                                                                       |
|    | 1PC                                                                                 |    | 1PC                                                                                 |    |                                                                                       |
|    |                                                                                     |    |                                                                                     |    |                                                                                       |




STEP 1

| A                                                                                                           | D                                                                                             |
|-------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
| <br>M $\frac{1}{4}$ "x50 | <br>Ø38x20 |
| 3 PCS                                                                                                       | 2 PCS                                                                                         |





STEP 2

| A                                                                                                             | D                                                                                               |
|---------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|
| <br>M $\frac{1}{4}$ "x50 | <br>Ø38x20 |
| 8 PCS                                                                                                         | 2 PCS                                                                                           |





STEP 3

|                                                                                     |
|-------------------------------------------------------------------------------------|
| F                                                                                   |
|  |
| M4x15                                                                               |
| 10PCS                                                                               |



STEP 4

|                                                                                       |
|---------------------------------------------------------------------------------------|
| F                                                                                     |
|  |
| M4x15                                                                                 |
| 10PCS                                                                                 |





STEP 5

C

M $\frac{1}{4}$ "x15

12 PCS





STEP 6

C



M $\frac{1}{4}$ "x15

3 PCS






STEP 7

|                                                                                     |
|-------------------------------------------------------------------------------------|
| A                                                                                   |
|  |
| M $\frac{1}{4}$ "x50                                                                |
| 12 PCS                                                                              |






STEP 8

| A                                                                                                           | D                                                                                             |
|-------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
| <br>M $\frac{1}{4}$ "x50 | <br>Ø38x20 |
| 4 PCS                                                                                                       | 1 PC                                                                                          |




STEP 9

| A                                                                                   | E                                                                                   |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |
| M $\frac{1}{4}$ "x50                                                                | Ø32x20                                                                              |
| 4 PCS                                                                               | 1 PC                                                                                |




## STEP 10




| A                                                                                   | B                                                                                   |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |
| M $\frac{1}{4}$ 'x50                                                                | M $\frac{1}{4}$ 'x35                                                                |
| 4 PCS                                                                               | 2 PCS                                                                               |

## STEP 11





| B                                                                                     |
|---------------------------------------------------------------------------------------|
|  |
| M $\frac{1}{4}$ 'x35                                                                  |
| 2 PCS                                                                                 |





# STEP 12

| A                                                                                   | B                                                                                   |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |
| M $\frac{1}{4}$ "x50                                                                | M $\frac{1}{4}$ "x35                                                                |
| 4 PCS                                                                               | 4 PCS                                                                               |



STEP 13

| A                                                                                                        | B                                                                                                        |
|----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|
|  M $\frac{1}{4}$ "x50 |  M $\frac{1}{4}$ "x35 |
| 4 PCS                                                                                                    | 4 PCS                                                                                                    |



## STEP 14

