








NAN-WK-086-GG




IMPORTANT: DON'T FASTEN BOLTS UNTIL ALL PARTS IN POSITION.

PART


A  x1	B  x1	C  x1
D  x2	E  x1	F  x2
G  x1		
1  M6x30 X6	4  X1	
2  M6X12 X5	5  M8 X6	
3  M6x40 X10		

1



3 X10

2




2 X5

4 X1

5 X6

⑥



① x6