
Assembly Instructions



Conference Table

Model No.

HOGA-JW0716/ HOGA-JW0903 HOGA-JW1045


Contact Us We're here to help you.



Your satisfaction is our top priority. If you encounter any issues with this product, such as missing or damaged parts, we're here to help. Please retain the original packaging and take photos of the packaging and the product, then contact us as soon as possible.


Warm Tips

- 1. Carefully read these instructions and keep them for future reference.
- 2. Check the parts list and confirm everything's there before starting assembly.
- 3. When assembling, put all parts on a soft, smooth surface like a carpet to avoid scratches.
- 4. Don't fully tighten screws until all parts are confirmed in place to avoid misalignment.




We recommend using hand tools for assembly.


If an electric screwdriver is used, reduce power and torque to avoid damage to the product.



AVOID SCRATCHES

In order to avoid scratching, this furniture should be assembled on a soft surface, such as a rug.









Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for a free replacement if you encounter any damaged or missing parts.


Parts List




Hardware List


Α	X10+1	В	X10+1	С	X8+1	D	X10+1	Е	X10+1	F	X1	G	X16+1
												@	
Ø6X35 mm		Ø15X12 mm		Ø8X30 mm		Ø10X	Ø10X50 mm Ø7		47 mm M4X5		55 mm M6X12 mm		12 mm
	Н	X8+1		X8+1	J	X4+1	K	X16+1	L	X4	М	X2	
	M6X30 mm		M6X	X35 mm M6X		40 mm	M6X55 mm		M6XØ30 mm		Ø20 mm		





В	X6	С	X4		
**					
Ø15X	12 mm	Ø8X30 mm			







X16


(d)

M6X12 mm
























Τ	X8	L	X4		
M6X3	30 mm	M6XØ30 mm			





Thank you for your support!

