




*Boraam Industries*

**RASMUS DINING CHAIR  
ASSEMBLY INSTRUCTIONS**





**PLEASE READ ME FIRST**



- Have questions about assembling your item?



- Item or parts damaged?



- Missing a part?



- We're here to help!




(847)949-6300 (M-F, 9am-5pm CST)




[www.boraamindustries.com](http://www.boraamindustries.com)




[customerservice@boraamindustries.com](mailto:customerservice@boraamindustries.com)




9PCS




9PCS




2PCS




3PCS



4PCS




2PCS




1PC


1






2



3






# 01






DO NOT TIGHTEN BOLT COMPLETELY

# 02






DO NOT TIGHTEN BOLT COMPLETELY

# 03




DO NOT TIGHTEN BOLT COMPLETELY

# 04





DO NOT TIGHTEN BOLT COMPLETELY



BE SURE TO CHECK ALL BOLTS SECURELY  
TIGHTENED PRIOR USING THIS CHAIR



*Boraam Industries*  
**RASMUS EXTENSION DINING TABLE**  
ASSEMBLY INSTRUCTIONS





**PLEASE READ ME FIRST**



- Have questions about assembling your item?



- Item or parts damaged?



- Missing a part?



- We're here to help!



(847)949-6300 (M-F, 9am-5pm CST)




[www.boraamindustries.com](http://www.boraamindustries.com)




[customerservice@boraamindustries.com](mailto:customerservice@boraamindustries.com)







**12PCS**  
**M10\*10**



**12PCS**  
**M10\*30**




**12PCS**  
**M10\*60**





**1PC**  
**Allen Wrench**  
**M17\*100**


①




②




③




# 01




# 02




**03**




**04**




**05**



**06**





BE SURE TO CHECK ALL BOLTS SECURELY  
TIGHTENED PRIOR USING THIS TABLE