

V-5000 INSTALLATION

CPV-5000 INSTALLATION

-

The Universal Valve Trim kit includes two Spindle Adapters that allow for both shallow and deep valve mount installations. Measure the distance between the front lip of the Wall Mounting Plate and the end of the Valve Spindle as shown below to determine correct selection of Spindle Adapter.

- If the measurement falls between 1-7/8" to 2-1/2", the Spline Adapter marked "A" is needed for installation.
- If the measurement falls between **1-3/8" to 1-7/8"**, the Spline Adapter marked **"B"** is needed for installation.





Confirm that the Valve is in the off position. Insert Spline Adapter ① (Spline Adapter selection determined in **STEP 3**) over Valve Spindle ②. One set of splines on the adapter must be oriented perfectly vertical when installed, as shown below. Secure the Spline Adapter with the 8-32 X 3/8" Screw ③ provided.





11

10

Orient the Decorative Wall Plate ① as shown below and insert the RED index button into the top hole of the Wall Plate, and the BLUE index button into the lower hole. Slide Wall Plate Assembly over Wall Mounting Plate ②.



Orient the Handle Assembly in a vertical position as shown below. Guide Handle Assembly onto the Spline Adapter (3). While holding the Handle (1) stationary in the vertical position, thread the Handle Escutcheon (2) onto the Wall Mounting Plate (4). Hand tighten until snug.



NOTE: After Handle Assembly installation, rotate Handle counterclockwise to achieve full closure of Valve. If the Handle does not rest in a vertical position, repeat Steps 9 and 11 for proper Handle alignment.

ROUGH-IN DIMENSIONS: CPT-1000-TP

Dimensions are subject to change without notice.



REPAIR PARTS

