




















NAN-WK-017-GG



IMPORTANT: DON'T FASTEN BOLTS UNTIL ALL PARTS IN POSITION.


PART

A  X1	B  X1	C  X1
D  X1	E  X1	F  X3
G  X3	H  X3	I  X3
J  X3	K  X1	L  X1
M  X1	N  X2	O  X2
P  X1	Q  X1	R  X2
S 	T 	U 


PARTS

①			24PCS	⑦		3PCS
②			12PCS	⑧		M6x40 20PCS
③			M4X35 12PCS	⑨		M6x15 8PCS
④			M4X14 28PCS	⑩		M6x55 4PCS
⑤			M4X18 6PCS	⑪		8PCS
⑥			3PCS	⑫		M8 4PCS

1





2




V2

3



4 X12


4



1 X12

2 X12



5



8 X2


11 X2

6



9 X 8


7



8 X 10

12 V 1


8



8 X8


11 X6

9



10 X4

10



4x4

11

