




















Assembly instruction B










Assembly instruction B




① x1 	② x3 	③ x1 
④ x4 	⑤ x8 	⑥ x2 
⑦ x9 	⑧ x4 	⑨ x1 
⑩ x2 	⑪ x2 	⑫ x28 
⑬ x2 	⑭ x1 	⑮ x1 
⑯ x1 	⑰ x2 	⑱ x4 
⑲ x1 	⑳ x4 	㉑ x1 

Hardware List

A×32 (2+extra)  M8×20mm	B×17(1+extra)  M6×55mm	C×4  M6×40mm
D×15 (1+extra)  M6×32mm	E×26 (1+extra)  M6×15mm	F×49 (4+extra)  M6×10mm
G×8 (1+extra)  M6×15mm	H×2  M4	I×2 
J×2  M8×40mm	K×2  M5×40mm	

1

Step 1




F×32pcs




M6×10mm

Step 2



2



E×8pcs




M6×15mm

x 2


3



A×8pcs




M8×20mm




x 2

4




B×4pcs




M6×55mm

D×4pcs




M6×32mm



x 2

5





F×8pcs



M6×10mm

6




A×4pcs



M8×20mm


7




E×4pcs



M6×15mm




8



A×4pcs




M8×20mm




9

C×2pcs



M6×40mm




10

F×1pc




M6×10mm

Step 1



Step 2



11

E×4pcs




M6×15mm

G×4pcs




M6×15mm



12

B×1pc




M6×55mm

D×2pcs



M6×32mm






Ex2pcs



M6×15mm




12


Dx1pc





M6×32mm




13



14




D×4pcs

M6×32mm
E×4pcs

M6×15mm
G×4pcs

M6×15mm


15



A×8pcs




M8×20mm



x 2

16

B×4pcs




M6×55mm

D×4pcs




M6×32mm



x 2


17




A×4pcs



M8×20mm




18




A×4pcs




M8×20mm




19




C×2pcs



M6×40mm



20




Watch out for pinching your hands

21



B×3pcs



M6×55mm



22



Tighten all screws 100%