



# Assembly Instructions




A1




x2

A2




x2

B1




x2

B2



x2

C



x2

D



x4

E




x4

F




x2

G



x2

H




x2

I




x1

J1




x1

J2




x1

K1



x1

K2




x1

L



x120

M




x 20

N




x 8

1




x2

2




x2

3








x1


4




x1

1







G




G



H




H




I


3



4



5



6

