






3





4




9 X4

5




6 X3
9 X3
11 X3

1




- ② X4
- ③ X16
- ⑩ X4

2









- ① X4
- ④ X4
- ⑤ X4
- ⑧ X4

3




- ② X4
- ④ X4

PART

 (A)	 (B)	 (C)	x2
 (D)	 (E)	 (F)	x3
 (G)	 (H)	 (I)	x1
 (J)			
 (1)	M6x55 4PCS		
 (2)	M6x30 8PCS		
 (3)	20PCS		
 (4)	M6x12 8PCS		
 (5)	M6 4PCS		
 (6)	M6x20 3PCS		

NAN-WK-059-GG



IMPORTANT: DON'T FASTEN BOLTS UNTIL ALL PARTS IN POSITION.