
INSTRUCTIONS

Product Picture



Product Instructions





Movement Sensor [Pir] 150° 3-5 Meter Detection Range

RUTO OFF 20 Sec After No Movement Built in light sensing device






- 1x O ON
- 2x ♥ Induction Mode (the light turns on when the human body is active in the dark environment)
- 3x ♥ OFF

► Mode 2



Press and Hold The Button For Three Seconds To Enter The Stepless Dimming Mode.Release The Hand To Maintain The Current Brightness; Press And Hold The Key Again For Three SecondsTo Enter The Reverse Dimming. (Dimming Range 10%-100%)(Dimming is Available In The Constant Light Mode And Induction Mode)

Charging method





Charging indicator

- 🔆 The red light is on during charging
- K Green light after charging

Matters Needing Attention

- 1. Do not install it near the inlet and outlet of cold and hot air in a humid environment, strong light exposure, so as not to affect the sensitivity and cause wrong action.
- 2. If the light is not on for the first time, please charge it before use.
- 3. When the light is dim and the battery is exhausted, please charge the product in time.
- 4. The sensing area of the product surface cannot be covered by other objects. When cleaning the product surface, it is necessary to wipe it with a soft dry cotton cloth.
- 5. Do not place the product on an unstable surface to prevent damage to the lamp body and sensor due to collision.
- 6. In case of failure during the warranty period, please do not disassemble this product without permission, otherwise it will not be guaranteed.















