CARE AND MAINTENANCE

Spot clean using a mild water-free solvent. Only a professional cleaner should undertake a complete overall cleaning.

The use of steam or water-based cleaners may cause excessive shrinking or staining.

NOTICE

- * Please make sure that you have all parts indicated before you begin assembly of this item.
- * This item should be assembled on a soft surface to prevent scratching the finish during assembly.
- * This item may require periodic tightening.


Part List and Hardware List

PIECE	DESCRIPTION	PICTURE	QUANTITY
А	TOP PANEL		1X
В	LEFT ASSEMBLY		1X
С	RIGHT ASSEMBLY		1X
D	TOP RAIL		1X
E	FRONT RAIL		2X
F	BOTTOM PANEL		1X
G	SIDE BACK PANEL		2X
Н	MIDDLE BACK PANEL	<i></i>	1X
I	LEG FRAME	/	2X
J	BASE FRAME		1X
К	DRAWER FRONT	<u></u>	3X
L	DRAWER LEFT		3X
М	DRAWER RIGHT	_	3X
N	DRAWER BACK		3X
0	DRAWER BASE		3X
Р	DRAWER SUPPORT	_	3X



Model# CHS5002A

Product Dimensions: 34 1/2"W x 18"D x 36"H



WEIGHT CAPACITY: TOP: 110 LBS DRAWER: 30 LBS


WARNING: DO NOT OVER TORQUE BOLTS/SCREWS

PIECE	DESCRIPTION	PICTURE	QUANTITY
1	30 MM BOLT	M6x30mm	12X
2	1" ROUND HEAD SCREW	M3x25mm (humum)	3X
3	1 1/4" FLAT HEAD SCREW	M3x32mm	33X
4	3/4" FLAT HEAD SCREW	M3x19mm	18X
5	CAMBOLT	∞	38X
6	CAMLOCK	3	38X
7	HANDLE		6X
8	MACHINE SCREW	M4x25mm (12X
9	WOODEN DOWEL		8X
10	SPRING WASHER	0	8X
11	FLAT WASHER	0	8X
12	ALLEN KEY		1X

Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.

If any part is missing or damaged, do not attempt to assemble the product.


Estimated Assembly Time: 60 minutes.



Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.

If any part is missing or damaged, do not attempt to assemble the product.

Estimated Assembly Time: 60 minutes.



Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.


If any part is missing or damaged, do not attempt to assemble the product.

Estimated Assembly Time: 60 minutes.

Tools Required for Assembly : Phillips Screwdriver

FLAT WASHERS. ATTACH BOLTS USING ALLEN KEY.

NOTE: DO NOT OVER-TIGHTEN THE BOLTS.



NOTE: TIGHTEN ALL BOLTS FROM STEP 5.


C3D. 5585 / 20 / 01

Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.

If any part is missing or damaged, do not attempt to assemble the product.

Estimated Assembly Time: 60 minutes.

Tools Required for Assembly : Phillips Screwdriver




SCREWS. ATTACH DRAWER SUPPORT TO UNIT USING 1 1/4" FLAT HEAD SCREWS.

Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.

If any part is missing or damaged, do not attempt to assemble the product.

Estimated Assembly Time: 60 minutes.



Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list. If any part is missing or damaged, do not attempt to assemble the product.

Estimated Assembly Time: 60 minutes.

