











A  Φ 8*30 26pcs	B  2pcs	C  2pcs	D  Φ 3. 5*14 34pcs	E  Φ 3. 5*25 8pcs	F  4pcs	G  1pcs	H  2pcs	I  8pcs
J  4pcs	K  1pcs	L  4pcs						



1





X2



A	$\Phi 8*30$	D	$\Phi 3.5*14$	I
				
16pcs		4pcs		4pcs

2




A	$\Phi 8*30$	D	$\Phi 3.5*14$	I	E	$\Phi 3.5*25$	F
							
8pcs		4pcs		4pcs	8pcs		4pcs

3




4




Pay attention to the positive and negative poles



5




6





7




8



9



10



Please remove the protective plastic film after the whole assemble process finished, then the surface will be high glossy, thank you for your choice