


Measuring Guide (Blinds or Shades)

**Do Not make any deductions or allowances*


**To measure, use a metal measuring tape (cloth tapes may stretch).*

INSIDE MOUNT



Blinds or Shades are mounted inside the window casing or frame. Measure the width in the three different places shown for narrowest width.

Measure the Height from the top of the window opening to the top of the window sill in the three different places shown for the smallest height.



Measure exactly to the nearest 1/8 in. Depth measurement must exclude any locks, levers or handles.

OUTSIDE MOUNT

Blinds or Shades are mounted outside the window casing/frame.



Measure the exact Width and Height of the entire area to be covered.

For added light control and privacy, we recommend you add 1 1/2" on each side. (approximately 3" for the overall width and height)

Measure exactly to the nearest 1/8 in. Select the width and height closest to the area you want to cover.

**Do not order blinds/shades less than the area you want to be covered.*

← Add 1 1/2" to each side →



Recommended to add 3"