













ASSEMBLY INSTRUCTION




PARTS AND HARDWARE LIST

1		2 PCS			
2		2 PCS			
3		1 PC			
4		1 PC			
5		2 PCS			
6		2 PCS			
7		1 PC			
8		2 PCS			
9		2 PCS			
10		1 PC			
11		1 PC			
12		10 PCS			
13		2 PCS			
A	 M8*45mm  M8	8 PCS	F	 M6*35mm	4 PCS
B	 M6*45mm  M6	8 PCS	G	 M6*30mm	2 PCS
C	 M6*17mm  M6*10mm	8 PCS	H	 M6 4mm	1 PC
D	 M8*55mm	2 PCS	I	 M8 5mm	1 PC
E	 M6*55mm	1 PC			

STEP 1




3



1 PC

STEP 2




4



1 PC

STEP 3




7



1 PC

STEP 4





7





1 PC

STEP 5





5		2 PCS	C	M6*17mm M6*10mm	8 PCS
6		2 PCS	H	M6 4mm	1 PC

STEP 6



1		2 PCS			
B	M6*45mm M6	4 PCS	H	M6 4mm	1 PC


STEP 7



2*2


2		2 PCS			
B	M6*45mm	4 PCS	H	M6 4mm	1 PC

STEP 8



A	M8*45mm	8 PCS			
I	M8 5mm	1 PC			


STEP 9



8		2 PCS
---	---	-------

9		2 PCS
---	---	-------



STEP 10



10		1 PC
----	---	------


11		1 PC
----	---	------

STEP 11




D		M8*55mm	2 PCS			
E		M6*55mm	1 PC			
F		M6*35mm	4 PCS	H		M6 4mm 1 PC
G		M6*30mm	2 PCS	I		M8 5mm 1 PC

STEP 12




12		10PCS
-----------	--	-------

STEP 13



12		10PCS
----	---	-------

STEP 14



13		2 PCS
----	---	-------