

IMPORTANT:

Installation Instructions

We recommend wet cutting or the score and snap method during the installation process. Improper installation techniques could expose installer to harmful silica dust.

Do not dry cut product using power tools during the installation process. Using dry cutting methods could present a risk of acute lung injury. If adequate ventilation cannot be achieved, wear a mask or respirator. For more information, see the SDS at www.anatolia.com.

IMPORTANTE:

Instrucciones de Instalación

Para el proceso de instalación se recomienda hacer los cortes mojados o usar el método de marcar y cortar. Las técnicas de instalación inadecuadas podrían hacer que el instalador se exponga al nocivo polvo de sílice.

Durante la instalación, el producto no debe cortarse en seco utilizando herramientas eléctricas. El utilizar métodos para cortar en seco podría presentar un riesgo de lesión pulmonar aguda. En caso de no poder ventilar el área de trabajo adecuadamente, se deberá utilizar una mascarilla o respirador. Para más información, consulte la hoja de datos de seguridad en www.anatolia.com.