

HO9521A0TX / HO9521B0TX

Industrial Restoration


Drafting Table

Assembly Instructions



Southern
ENTERPRISES

For assistance with assembly, contact:
Southern Enterprises, Inc.
Customer Service: 1-800-633-5096
service@seidal.com
www.seidal.com












PO# :

"Please do not load more than 30 lb. when table top is fully raised".

Industrial Restoration Drafting Table

Parts List

Please review all parts and hardware before disposing of any packaging. Before beginning assembly, separate each type of hardware. Carefully study the diagrams below and check that you have all parts indicated. Call Customer Service if missing hardware. Using the incorrect hardware will cause damage.


A. Quantity of 1  Top Panel	B. Quantity of 1  Left Leg Frame	C. Quantity of 1  Right Leg Frame
D. Quantity of 1  Back Stretcher		
1. Quantity of 4  Small Bolts $\varnothing 1/4" \times 3/4"$	2. Quantity of 8  Bolts $\varnothing 1/4" \times 1-5/8"$	3. Quantity of 12  Flat Washers
4. Quantity of 12  Flat Washers	5. Quantity of 1  Allen Wrench	

Care and Cleaning Instructions:

Before using, wipe with a clean, dry cloth.
 Periodically apply furniture wax to renew the finish.
 Avoid rubbing or scratching the surface with rough or abrasive objects.

For replacement parts or questions, please call customer service at 1-800-633-5096.

Assembly Tool Required:
 No.2 Phillips Screwdriver (Not Included)



Industrial Restoration Drafting Table

Assembly Instructions




Figure 1

Attach Left Leg Frame **(B)** and Right Leg Frame **(C)** to Back Stretcher **(C)** using Small Bolts **(1)**, Spring Washers **(3)** and Flat Washers **(4)**.

Tighten bolts with Phillips screwdriver.





Figure 2


Insert assembled unit into Top Panel **(A)**.



Insert Bolts **(2)**, Spring Washers **(3)**, and Flat Washers **(4)** into holes in Leg Frames.

Tighten bolts with Allen Wrench **(5)**.

Figure 3



To open top, simply pull up. Guide back down to close.

Now your Industrial Restoration Drafting Table is ready to use!

Figure 4

Parts Replacement Form

Customer Information

Name

Address

City/State/Zip Code

Phone Number

Please indicate where you purchased this item: Store/Website/Catalog

Please indicate color/size/style number:

Style No	Parts Letter	Parts Description	Quantity Needed
----------	--------------	-------------------	-----------------

----------------------	----------------------	----------------------	----------------------

----------------------	----------------------	----------------------	----------------------

----------------------	----------------------	----------------------	----------------------

Please immediately examine this product carefully. Any request for missing parts or damage replacement must be received within 90 days of your receipt of the product. Replacement, if available, will be honored within this time frame. Parts will not be available for items arriving fully assembled. We do not recommend modifying product(s) and we are not responsible for any damages due to product modification(s). If damages or missing parts are not reported within 90 days of your receipt, we are under no obligation to provide parts or replacement merchandise.

For product issues, please contact Southern Enterprises at 800-633-5096 (toll-free) / 972-869-0111 (Dallas), Mon-Fri 9am – 4pm CST, or email us at service@seidal.com. Please ask for customer service representative for issues involving damages or replacement parts. Please ask for technical assistance representative for any issues with product and assembly/construction.

Please contact the retailer that you purchased from for returns.



Southern
ENTERPRISES

Customer Service: 1-800-633-5096
service@seidal.com

Southern Enterprises, Inc.
600 Freeport Parkway, Suite 200
Coppell, Texas 75019