For Style 9605P9 **Assembly Instruction Sheet #IS-9605P9**


Light Source: (1) E26 Bulb 60W Maximum(Not Include).
Estimated Assembly Time: 15-30 minutes **Fools Required:** Flathead screwdriver, Phillips screwdriver, pilers, wire cutters, wire strippers, electrical tape, safety glasses

Preparation: Identify and inspect all parts before beginning installation. Check package content list and diagrams below to be sure all parts are present. If any parts are missing or damaged, do not attempt to assemble, install, or operate the fixture. Contact customer service for replacement

∆Warnings and Cautions

We strongly recommend that a licensed, professional electrician perform the installation. These instructions are provided for your safety. It is very important you read them completely before installing the fixture. Turn off electricity at circuit breaker or main fuse box before installation. Consult a licensed electrician if in doubt.

Disconnect fixture from power source before replacing bulbs. Make sure bulbs are given sufficient time to cool before removal.



Hardware Contents

A.Pass the supply wires through the Mounting bracket (EE) Гighten until snug. Secure it with Outlet Box with the head of the Green Ground Screw facing you Attach the Mounting bracket (EE) to the Outlet Box Outlet Box Screws Ground Wire Figure 2 Outlet Box m ဂ္ဂ

STEP 3 - Fit Backplate to Mounting bracket Assembly

A. Fit the backplate to Mounting Screws (DD) and secure Mounting bracket (EE) until the and Lock Washer and Mounting Screws (DD) by secure, remove the Screws (DD) in or out of the then screwing Mounting If not, adjust the length of the be snug against the ceiling and the Decorative Caps (AA) with Decorative Caps (AA). Note: The backplate should Ceiling Canopy ġ


STEP 1 - Attach Mounting Screws, Lock Washers


A. Line up a set of holes on the and Hex Nuts to Mounting bracket.

on the Backplate.

Hand tighten until snug. Screws (DD). Nuts onto the Mounting Washers and thread Hex Mounting bracket (EE). Pass Lock into the holes on the Thread Mounting Screws (DD) Mounting bracket(EE) and Holes

Figure 1





2 of 2