Measuring Guide (Blinds or Shades)

*Do Not make any deductions or allowances *To measure, use a metal measuring tape (cloth tapes may stretch).


.....

INSIDE MOUNT



Blinds or Shades are mounted inside the window casing or frame. Measure the <u>width</u> in the <u>three</u> different places shown for narrowest width.

Measure the <u>Height</u> from the top of the window opening to the top of the window sill in the <u>three</u> different places shown for the <u>smallest height</u>.



Measure exactly to the nearest 1/8 in. <u>Depth</u> measurement must exclude any locks, levers or handles.

OUTSIDE MOUNT

Blinds or Shades are mounted outside the window casing/frame.

Measure the <u>exact Width and Height</u> of the entire area to be covered.

For added light control and privacy, we recommend you add 1 $\frac{1}{2}$ " on each side. (approximately $\frac{3}{2}$ " for the overall width and height)

Measure exactly to the nearest 1/8 in. Select the width and height closest to the area you want to cover.

*Do not order blinds/shades less than the area you want to be covered.

