



## Carillon® Rectangle Wading Pool®

Vessel bathroom sink

**K-7799**

### Features

- Rectangular basin with subtle lift at edges.
- Wading pool design accommodates a wide variety of faucets.
- No faucet holes; requires wall- or counter-mount faucet.

### Material

- Vitreous china.


### Installation

- Vessel.

### Recommended Products/Accessories

K-23726 Drain treatment

K-23725 Cast iron cleaner



**ADA**

**CSA B651**

### Codes/Standards

ASME A112.19.2/CSA B45.1

ADA

ICC/ANSI A117.1

CSA B651

### KOHLER® One-Year Limited Warranty

See website for detailed warranty information.

### Available Colors/Finishes

*Color tiles intended for reference only.*

| Color                                                                               | Code | Description   |
|-------------------------------------------------------------------------------------|------|---------------|
|  | 0    | White         |
|  | 96   | Biscuit       |
|  | NY   | Dune          |
|  | 95   | Ice™ Grey     |
|  | 58   | Thunder™ Grey |
|  | 7    | Black Black™  |

1-800-4KOHLER (1-800-456-4537)

Kohler Co. reserves the right to make revisions without notice to product specifications.

For the most current Specification Sheet, go to [www.kohler.com](http://www.kohler.com).

8-16-2022 22:51 - US/CA/MX



THE BOLD LOOK  
OF **KOHLER®**



## Carillon® Rectangle Wading Pool®

Vessel bathroom sink

**K-7799**



### Technical Information

All product dimensions are nominal.

Bowl configuration: Single

Installation: Drop-in, Vessel

Bowl area (Only):

- Length: 21-1/8" (536 mm)
- Width: 14-9/16" (370 mm)
- Bowl depth: 4-1/8" (105 mm)
- Water depth: 4-1/8" (105 mm)

Template: 1242828, required, included

### Notes

Install this product according to the installation instructions.

**NOTICE:** Countertop manufacturer or cutter must use the cut-out template provided with the product, or a current one provided by Kohler Co. (call 1-800-4-KOHLER). Kohler Co. is not responsible for cutout errors when the incorrect cut-out template is used.

ADA, CSA B651 compliant when installed to the specific requirements of these regulations.