

INSTALLATION




50 Hz / 60 HzCeiling Lamp 100 - 240V





MAX:60W



Installation:

- by screws on the Fix the crossbar ceiling.
- 2 Connect the cable.
- (3) Mount the lamp body.
- 4) Fix the metal tube.
- (5) Put the light source.
- 6 Put the crystal.

Cautions:

- Should be installed by professional
- person buring the cleaning and
- power off Do not install the lamp on the ceilin installation remember to cut the
- environment ventilation and dry. that is wet and keep the installation
- Keep the lamps away from corrosive chemical and air such as acid and alkali.
- Do not wash it with water, but wipe it clean with a soft cloth.

4	3	2	1	No	
The lampshade	Light Source	hanging board	Screw	Part Name	Accessory
					ory List
—	<u> </u>	Н	<u> </u>	QTY	