



Son: Identify and inspect all parts before beginning installation. Check package content list and diagrams below to be sure all parts are If any parts are missing or damaged, do not altempt to assemble, install, or operate the thiure. Contact customer service for replacement quiver: Helfred coverdiver, Philip ree: (2) Et2 Base Bath 60V Medimen. I Assembly Time: 15-50 minutes diver, Philips screwdiver, plans, who culture, who stippers, electrical tops, eatily glasses. BW Machimur(Not Include).

## Warnings and Cautions

We strongly recommend that a licens um off electricity at circuit breater or main fuse box before installation. Consult a floensed electrician if in doubt. hese instructions are provided for your safety. It is very important you read them completely before installing the foture. onal electrician perform the installation.

Disconnect fixture from power source before reptacing butbs. Make sure butbs are given sufficient time to cool before removal





C Fodure Body x1

D Foture Body x1