





















1  1400*400 1PS	2  695*383 1PS	3  695*383 1PS	4  695*383 1PS	
5  676.5*60 4PS	6  676.5*60 4PS	7  676.5*60 1PS	8  676.5*60 1PS	
9  676.5*80 1PS	10  676.5*80 1PS	11  685*288 4PS	12  697*185 3PS	
13  697*185 3PS	14  627.5*110 6PS	15  300*110 6PS	16  300*110 6PS	17  635*294 6PS




Hardware installation demonstration

NOTE: Please make sure "A" hardware tightened and can't be pulled out!


I



II



III







IV



Scan QR code for assembly video

1











A*33




G1*24

2







E*24




I1*6

3

Make sure the arrow on the screw align to the hole on the side.






B*7




C*5

4






B*13



C*5

5






B*7



C*5

6






B*6



C*6

7

X3




G2*12



D*6






F*12




H*3

8




X3



	D*12
	I2*3
	J*6
	K*12

9

X3




G2*12



D*6






F*12




H*3

10

X3



D*12



I2*3




J*6




K*12

11



12









D*16



L*16

13



M*2

Please install tip-proof fitting.