## 50 Hz/60 HzCeiling Lamp MAX:60W 100-240V ယ INSTALLATION N 0 50Hz/60Hz 100-240V 9 **( (2)** 0

## Installation:

- Z Insert the expansion bolt in the ceiling.

  3 Mount the crissbar by screws.

  Preson the cleaning and installation remember to cut the power off
- 4 Connect the cable.
- 5 Mount the bracket.
- 6 Put the lamp shade and light source.

## Cautions:

- Should be installed by professional
- Keep the lamps away from corrosine chemical and air such as acid and alkali.
- Do not wash it with water, but wipe it clean with a soft cloth.

4	ယ	2	<b>—</b>	₽	
The lampshade	Light Source	hanging board	Screw	Part Name	Accessory
				Photo	sory List
<u> </u>	<u> </u>	<u> </u>	<u> </u>	SE SE	