## **INSTRUCTION GUIDE**



BRASS CLEANOUT PLUG

- Ensure threads on cleanout are clean and free of debris.
- Apply an approved Oatey thread sealant to the threads of the Brass Cleanout Plug.



- Screw the Brass Cleanout Plug into the cleanout opening until hand tight.
- Using a pipe wrench or adjustable split ring pliers, finish tightening the Brass Cleanout Plug in place.
- Test to verify that the installation of the Brass Cleanout Plug has created a watertight seal. Run water from the nearest fixture on the same pipe run that the cleanout is located and visually inspect for leaks.
- If a leak occurs repeat steps 1-5 until a watertight seal is achieved.

©2020 Oatey SCS. All Rights Reserved. This information is based on data believed to be reliable but Oatey makes no warranties, express or implied, as to its accuracy and assumes no liability arising out of its use. The data listed falls within the normal range of product properties but should not be used to establish specification limits or used alone as the basis of design. Oatey's liability to purchasers is expressly limited to the terms and conditions of sale. Oatey is trademark of Oatey Co. All other trademarks can be found www.Oatey.com.