


Assembly Instructions




Bar Table

Model No.
HOGA-JW1150
HOGA-JW1151

Contact Us


We're here to help you.



Your satisfaction is our top priority. If you encounter any issues with this product, such as missing or damaged parts, we're here to help. Please retain the original packaging and take photos of the packaging and the product, then contact us as soon as possible.


Warm Tips

1. Carefully read these instructions and keep them for future reference.
2. Check the parts list and confirm everything's there before starting assembly.
3. When assembling, put all parts on a soft, smooth surface like a carpet to avoid scratches.
4. Don't fully tighten screws until all parts are confirmed in place to avoid misalignment.




We recommend using hand tools for assembly.


If an electric screwdriver is used, reduce power and torque to avoid damage to the product.



AVOID SCRATCHES

In order to avoid scratching, this furniture should be assembled on a soft surface, such as a rug.





















⚠ Caution

Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for a free replacement if you encounter any damaged or missing parts.


Parts List



1  2 pcs	2  1 pc	3  4 pcs	4  8 pcs	5  1 pc
6  1 pc	7  4 pcs	8  1 pc		

Hardware List


A	B	C	D	E	F
 M6x12mm 13 pcs	 M6x25mm 21 pcs	 Ø5x40mm 49 pcs	 8x30mm 4 pcs	 M8x80mm 2 pcs	 M8x14x8mm 4 pcs
G	H	I	J		
 M8 2 pcs	 M4x65mm 1 pc	 M3x65mm 1 pc	 M6xØ19mm 8 pcs		



1

A	H
	
M6x12mm 12 pcs	M4x65mm 1 pc






2

B

M6x25mm 4 pcs






3





C	I
	
Ø5x40mm	M3x65mm
24 pcs	1 pc

4




B

M6x25mm
4 pcs




screw down




5





C*24



C

Ø5x40mm
24 pcs


6





B

M6x25mm
4 pcs

screw down




7




J

M6xØ19mm
8 pcs


8




D	E
	
8x30mm	M8x80mm
2 pcs	2 pcs

F	G
	
M8x14x8mm	M8
2 pcs	1 pc


9





D	F
	
8x30mm	M8x14x8mm
2 pcs	2 pcs

G

M8
2 pcs

screw down 




10




B

M6x25mm
8 pcs

screw down 





Thank you for your support!

